




AUDI A3 SPORTBACK: 1YEV424			
Vinnumber:	WAUZZZGY1MA009977	Versionname:	2.0 30 TDi 85kW Advanced
First Registrationdate:	7/08/2020	Fiscalpower:	
Expertise Mileage:	29011	Power Kw:	85
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2201
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	225/45/17/91 V		
	Fr.L.	Hankook: 4 mm	Fr.R. Continental: 4 mm
	Re.L.	Hankook: 4 mm	Re.R. Continental: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			225/45 R 17 91 V
Tyre size FR			225/45 R 17 91 V
Tyre size RL			225/45 R 17 91 V
Tyre size RR			225/45 R 17 91 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			260
Tyre make FR			256
Tyre make RL			260
Tyre make RR			256
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1018,73
Bumper F, Dent(s) and scratch(es), Spot repair			144,58




Wing FL, Dent(s) and scratch(es), Repair and paint (complete)	300,51
---	--------




Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Outer sill L, Scratch(es), Acceptable	0,00
---------------------------------------	------



Central pillar L, Scratch(es), Acceptable	0,00
---	------



Boot cover, Missing, Forfeit	55,00
------------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

