



Audi A3: 2DJB449

Vinnumber:	WAUZZZGY1PA059301	Versionname:	
First Registrationdate:	27/03/2023	Fiscalpower:	
Expertise Mileage:	47702	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2414
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

225/45/17/91 H				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 17 91 H
Tyre size FR				225/45 R 17 91 H
Tyre size RL				225/45 R 17 91 H
Tyre size RR				225/45 R 17 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	Yes	Compressor:	No
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		

Total cost ex VAT	1540,98
Interior, Damaged, Acceptable	0,00



Bumper F, Scratch(es), Acceptable

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Door FL, Repaired, Acceptable

0,00



Door RL, Bad repair, Repair and paint (complete)

0,00



Wing RL, Bad repair, Repair and paint (complete)

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Compressor, Missing, Replace

287,33



Charging cable (normal), Missing, Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Wing FR, Scratch(es), Repair and paint (complete)

300,51



Door FR, Scratch(es), Repair and paint (complete)

434,50



Roof pillar R, Scratch(es), Polish

0,00



Roof, Dent(s), Repair and paint (complete)

0,00

