



Audi A3 (UKL): 2BDN650

Vinnumber:	WAUZZZGY2NA015885	Versionname:	A3 Sportback Business 30 2.0TDi 116pk/cv 5p S-Tronic
First Registrationdate:	13/10/2021	Fiscalpower:	
Expertise Mileage:	108730	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+11300km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/17/91 H			
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 91 H
Tyre size FR				225/45 R 17 94 V
Tyre size RL				225/45 R 17 91 H
Tyre size RR				225/45 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Spot repair



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)

