



Audi A3 (UKL): 1YVL779

Vinnumber:	WAUZZZGY3MA062065	Versionname:	A3 Sportback 30 2.0TDi 116pk/cv 5p
First Registrationdate:	4/01/2021	Fiscalpower:	
Expertise Mileage:	160500	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	Échéance dépassée de 6700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Type of Maintenance book	Digital maintenance	Type of Tow bar	No Tow bar
Type of GPS storage	N.A.		


Tyres

	205/55/16/91 H			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	7.0			
Tyre profile depth RR	6.0			
Tyre size FL	205/55 R 16 91 H			
Tyre size FR	205/55 R 16 91 H			
Tyre size RL	205/55 R 16 91 H			
Tyre size RR	205/55 R 16 91 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	259			
Tyre make RR	259			

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Compressor, Missing, Replace



Tyre repair kit, Missing, Replace



Boot lid covering R, Broken, Replace



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable



Wing RR, Scratch(es), Spot repair



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable

