














TECHNICAL CONDITION 

Engine	Brakes	Steering
Engine starts 	Brake operation 	Sounds normal 
Engine operation 	Clutch Clutch operation  Idle sounds normal  Clutch biting point 	Gear Box Automatic shift  Manual shif  Warning light OK 
Engine compartment dry (oil) 		
Fume quantity 		
Sounds normal 		






COMPLAINT NOTE 

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS 

Coolant fluid 
Brakes fluid 

EQUIPMENT TEST 

Electric windows test 
Audio equipment 
Navigation equipment 
AC / Heating system 
Central lock system test 













TYRES 


Profile depths	
FL 5 mm	FR 5 mm
BR 5 mm	BL 5 mm


Additional tyre profil depths


A 4 mm	B 4 mm
C 4 mm	D 4 mm

CONTROL LIGHTS 

Dashboard 
ABS 
Oil 
Airbag 
Engine 
Brakes 
Steering 
DPF 
Diesel heaters 
Traction control / ESP / Stability control 
4x4 
Alternator / Battery 

 No defects recognizable, good condition or positive tests based on vehicle's age and mileage.

 Registered damage that needs to be repaired by the buyer.

 Not verifiable.