

INSPECTION REPORT


End of contract


GENERAL INFO

File	300371
License plate	EV4815
Vehicle identification number	WAUZZZGY8NA026079
Dossier	2021216005
Make	Audi A3 SB 30 TFSI110 Advanced
Mileage	85948
First registration	24/11/2021
client availability date	01/12/2025
inspectionDate	02/12/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
283	Bumper Rear / Trim Right / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Damage within Renta-norm-





Wheel Alloy Rear Right // Repair-scratch





Wheel Alloy Front Right // Repair-scratch






Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch



Bumper Rear / Trim Right / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent