


Vehicle details

VIN	WAUZZZGY9 MA126576	Brand	AUDI	Maintenance date	-
Licence Plate	L0-95-KR	Model	A3 Sportback 35 TFSI S tronic S edition 5d	Maintenance mileage	-
Registration date	10/06/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	174 015 km	Engine size	1498	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	23/07/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Remote key	✓
Spare key	✗

Tyres

Continental 225/45/17 Summer 3.5 mm		Continental 225/45/17 Summer 3.5 mm	
Pirelli 225/45/17 Summer 4.0 mm		Continental 225/45/17 Summer 6.5 mm	

Exterior

3



●●●

Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4



●●●●

Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Replace

5



●●

Part	Door
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



●●

Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

7



●●

Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



●●

Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

10



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Other interior
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Gerookt in voertuig	