



Audi A3: 2BJS677

Vinnumber:	WAUZZZGY9NA030982	Versionname:	
First Registrationdate:	10/12/2021	Fiscalpower:	
Expertise Mileage:	98993	Power Kw:	110
Bodytype:		Parking lot	3332
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Black
Fueltype:	Hybrid Petrol		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		

Options

Steering wheel multifunctional		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of GPS storage	HD	Front parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Cruise Control			
Type of climate control	Autom climate control		
Type of headlighting	Headlighting Halogen		
Number of keys total	2		
Type of Lining	Lining leather		

Limited Technical Inspection

Tyres

Tyre size RL	225/45 R 17 91 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	3.0
Tyre profile depth RR	6.0
Tyre make FR	261
Tyre size FR	225/45 R 17 91 H
Tyre make RR	261
Tyre size RR	225/45 R 17 91 H

225/45/17/91 H

Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Tyre profile depth FL	3.0
Tyre make FL	261
Tyre size FL	225/45 R 17 91 H
Tyre type FR	Winter
Tyre profile depth RL	6.0
Tyre type RR	Winter
Tyre make RL	261

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	1		
Repair kit	Yes		

Total cost ex VAT	1317,73
Seat cover FL, Worn, Acceptable	0,00



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Door FL, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Charging cable (normal), Missing, Replace

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Bumper trim R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)

157,71



Mirror side repeater R, Scratch(es), Replace

63,24

