



BMW 2 GRAN COUPÉ: 1YLD630			
Vinnumber:	WBA11AK0007G82146	Versionname:	218iA (103kW)
First Registrationdate:	28/09/2020	Fiscalpower:	
Expertise Mileage:	79479	Power Kw:	103
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2503
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
	225/40/18/92 Y		
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Goodyear: 4 mm	Re.R.
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			225/40 R 18 92 Y
Tyre size FR			225/40 R 18 92 Y
Tyre size RL			225/40 R 18 92 Y
Tyre size RR			225/40 R 18 92 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			259
Tyre make RR			259
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1519,73
Bonnet, Stone chip(s), Acceptable			0,00



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)	0,00
---	------



Door RL, Dent(s) and scratch(es), Repair and paint (complete)	0,00
---	------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------





Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Tailgate / Boot, Dent(s), Acceptable	0,00
--------------------------------------	------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	434,50
---	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Door FR, Dent(s) and scratch(es), Acceptable	0,00
--	------

