



BMW 2 GRAN COUPÉ: 1YLD630				
Vinnumber:	WBA11AK0007G82146	Versionname:	218iA (103kW)	
First Registrationdate:	28/09/2020	Fiscalpower:		
Expertise Mileage:	79479	Power Kw:	103	
Bodytype:		Body colour	Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2503	
Fueltype:	Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar	
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/40/18/92 Y			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL			4.0	
Tyre profile depth FR			4.0	
Tyre profile depth RL			4.0	
Tyre profile depth RR			4.0	
Tyre size FL			225/40 R 18 92 Y	
Tyre size FR			225/40 R 18 92 Y	
Tyre size RL			225/40 R 18 92 Y	
Tyre size RR			225/40 R 18 92 Y	
Tyre type FL			Summer	
Tyre type FR			Summer	
Tyre type RL			Summer	
Tyre type RR			Summer	
Tyre make FL			256	
Tyre make FR			256	
Tyre make RL			259	
Tyre make RR			259	
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			1519,73	
Bonnet, Stone chip(s), Acceptable			0,00	



Bumper F, Scratch(es), Acceptable

0,00



Windscreen, Stone chip(s), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Door FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07





Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Tailgate / Boot, Dent(s), Acceptable	0,00
--------------------------------------	------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	434,50
---	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Door FR, Dent(s) and scratch(es), Acceptable	0,00
--	------

