



BMW 218: K404GJ

Vinnnumber:	WBA11AK0407H45393	Versionname:	218iA 100kW Gran Coupe
First Registrationdate:	21/01/2021	Fiscalpower:	
Expertise Mileage:	97291	Power Kw:	100
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	247
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment	
GPS		Lining Alcantara	
Autom climate control		Central consol F	
Windows electric F		Headlights Xenon/LED/Laser	
Radio multimedia		Front parking sensors	
		Rear parking sensors	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 40 / 18 / 92 / Y / Aluminium	7,0 mm	Goodyear	Summer
	Right	225 / 40 / 18 / 92 / Y / Aluminium	6,4 mm	Goodyear	Summer
Rear	Left	225 / 40 / 18 / 92 / Y / Aluminium	5,7 mm	Goodyear	Summer
	Right	225 / 40 / 18 / 92 / Y / Aluminium	5,2 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Chemical polution, Polish



Bodywork, Paint measurement, Acceptable

