



BMW 218i L597KG

Vinnumber:	WBA11AK0407J40450	Versionname:	218iA 100kW Gran Coupe
First Registrationdate:	9/06/2021	Fiscalpower:	
Expertise Mileage:	156847	Power Kw:	100
Bodytype:		Body colour:	Schwarz unilak
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	awl
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Sun Roof electric
Windows electric F		Panoramic roof
Radio multimedia		Central consol F
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Degree of wear

225/45/17 94 Y				
Summer tyres:	Fr.L.	Goodyear: 4,2 mm	Fr.R.	Goodyear: 4,2 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 3,3 mm
Tyre profile depth FL				4.2
Tyre profile depth FR				4.2
Tyre profile depth RL				4.0
Tyre profile depth RR				3.3
Tyre size FL				225/45 R 17 94 Y
Tyre size FR				225/45 R 17 94 Y
Tyre size RL				225/45 R 17 94 Y
Tyre size RR				225/45 R 17 94 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (partial)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

