



BMW 2 GRAN COUPÉ: 1YLY514				
Vinnumber:	WBA11AK0607G87822	Versionname:	218i (103kW)	
First Registrationdate:	5/10/2020	Fiscalpower:		
Expertise Mileage:	123740	Power Kw:	103	
Bodytype:		Body colour	Grey	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2820	
Fueltype:	Petrol			
Maintenance	NOT OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar	
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Winter tyres:	225/40/18/92 V			
	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 6 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/40 R 18 92 V
Tyre size FR				225/40 R 18 92 V
Tyre size RL				225/40 R 18 92 V
Tyre size RR				225/40 R 18 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				265
Tyre make RR				265
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			1842,28	
Service, Maintenance, Check			0,00	



Floor covering FL, Burned, Smart repair	113,74
---	--------



Floor covering FR, Burned, Smart repair	113,74
---	--------



Bumper F, Scratch(es), Spot repair	144,58
------------------------------------	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Door RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Tailgate / Boot, Scratch(es), Repair and paint (complete)	411,74
---	--------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------



Bumper moulding R, Dent(s) and scratch(es), Repair and paint (complete)	157,71
---	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Side window trim FR, Scratch(es), Acceptable	0,00
--	------



Roof, Dent(s), Paintless dent repair	93,06
--------------------------------------	-------

