


Vehicle details

VIN	WBA11AK08 07H34834	Brand	BMW	Maintenance date	01/01/1900
Licence Plate	K2-91-JR	Model	2 Serie Gran Coupé ½ 218i Corporate Executive 4d	Maintenance mileage	-
Registration date	06/01/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	149 016 km	Engine size	1499	interior Color	Black
Fuel	-	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	03/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 225/40/18 Summer 5.0 mm



Michelin 225/40/18 Summer 5.0 mm



Bridgestone 225/40/18 Summer 5.0 mm

Bridgestone 225/40/18 Summer 5.0 mm

Exterior

1



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair



2



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair



3



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair



4



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair



5



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair



6



Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair



8



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair



9



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair



10



Part	Step plate
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info



11



Part	Door
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



Interior damage

7



Part	Interior cleaning
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning



Comments

Opslagpark : Dekra Ayvens