



**BMW 2-Reeks Gran Coupe (UKL): 2AAY502**

Vinnnumber:	<b>WBA11AK0X07H81279</b>	Versionname:	<b>218i Gran Coupe (F44) 1.5i 136pk/cv 4p Aut.</b>
First Registrationdate:	<b>4/02/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>131511</b>	Power Kw:	<b>100</b>
Bodytype:		Type of rims (mounted)	<b>Aluminium</b>
Gearbox:	<b>Automatic</b>		
Transmission:			
Fueltype:			
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Certificate of Conformity	<b>Yes</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Type of Tow bar	<b>No Tow bar</b>
GPS			
Type of Maintenance book	<b>Digital maintenance</b>		
Type of GPS storage	<b>HD</b>		

**Tyres**

205/55/16/91 H				
Winter tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>7.0</b>
Tyre profile depth RR				<b>7.0</b>
Tyre size FL				<b>205/55 R 16 91 H</b>
Tyre size FR				<b>205/55 R 16 91 H</b>
Tyre size RL				<b>205/55 R 16 91 H</b>
Tyre size RR				<b>205/55 R 16 91 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>257</b>
Tyre make FR				<b>257</b>
Tyre make RL				<b>257</b>
Tyre make RR				<b>257</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

**Service, Maintenance, Check**



**Windscreen, Stone chip(s), Replace**



Wing RL, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Outside rear-view mirror base L, Scratch(es), Acceptable



Wing FL, Bad repair, Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Outside rear-view mirror base R, Scratch(es), Acceptable



Door FR, Bad repair, Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

