



BMW 2-Reeks Gran Coupe (UKL): 1YBH606

Vinnumber:	WBA11AM0307G05980	Versionname:	216d Gran Coupe (F44) 1.5d 116pk/cv 4p Aut.
First Registrationdate:	7/07/2020	Fiscalpower:	
Expertise Mileage:	117913	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	25000 km - 06/2027		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/17/91 Y			
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/45 R 17 91 Y
Tyre size FR				225/45 R 17 91 Y
Tyre size RL				225/45 R 17 91 Y
Tyre size RR				225/45 R 17 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning



Ignition key, Not functioning (well), Acceptable



Bumper F, Scratch(es), Spot repair



Bumper F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Acceptable



Alloy rim RL polished, Rust, Acceptable



Wing RL, Scratch(es), Acceptable



Wing RL, Repaired, Check




Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check

