



BMW 5-Reeks (MKL): 2BBW974

Vinnumber:	WBA11BN050CJ04887	Versionname:	518d Touring (G31) 2.0d 136pk/cv 5p Aut.
First Registrationdate:	24/09/2021	Fiscalpower:	
Expertise Mileage:	194214	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	225/55 R 17 97 W
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	5.0
Tyre profile depth RR	5.0
Tyre size FR	225/55 R 17 97 W
Tyre make FR	256
225/55/17/97 W	
Summer tyres:	
Fr.L.	Continental: 5 mm
Re.L.	Continental: 5 mm
Fr.R.	Continental: 5 mm
Re.R.	Continental: 5 mm
Tyre size RR	225/55 R 17 97 W
Tyre make RR	256
Tyre profile depth FL	5.0
Tyre size FL	225/55 R 17 97 W
Tyre make FL	256
Tyre profile depth RL	5.0
Tyre type FR	Summer
Tyre type RR	Summer
Tyre make RL	256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Roof liner, Stain, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Bad repair, Repair and paint (complete)



Door RL, Bad repair, Repair and paint (complete)



Wing RL, Bad repair, Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Paintless dent repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

