



BMW 5 TOURING: 1YLN230			
Vinnnumber:	WBA11BN060CF54700	Versionname:	518d Aut. (100 kW)
First Registrationdate:	30/09/2020	Fiscalpower:	
Expertise Mileage:	147485	Power Kw:	100
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3401
Fueltype:	Hybrid Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
	225/55/17/92 H		
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.
	Re.L.	Uniroyal: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/55 R 17 92 H
Tyre size FR			225/55 R 17 92 H
Tyre size RL			225/55 R 17 92 H
Tyre size RR			225/55 R 17 92 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			265
Tyre make FR			265
Tyre make RL			265
Tyre make RR			265
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2353,11
Door panel FR, Scratch(es), Acceptable			0,00



Backrest cover FL, Scratch(es), Acceptable 0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 346,88




Wing RL, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Sill trim L, Scratch(es), Repair and paint (complete) 508,55



Door FL, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Repair and paint (complete) 521,40



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Dent(s), Repair and paint (complete)	846,62
--	--------

