



BMW X1 (UKL): 2CXE958

Vinnumber:	WBA11EG0005W19685	Versionname:	X1 (U11) sDrive 18d 2.0d 136pk/cv 5p Aut.
First Registrationdate:	3/01/2023	Fiscalpower:	
Expertise Mileage:	82663	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	binnen 9000km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/17/97 W				
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 7 mm	Re.R.	Hankook: 7 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/60 R 17 97 W
Tyre size FR				205/60 R 17 97 W
Tyre size RL				205/60 R 17 97 W
Tyre size RR				205/60 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Not functioning (well), Check



Door RL, Dent(s), Paintless dent repair



Tyre repair kit, Missing, Check



Compressor, Missing, Check



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

