



|                                          |                       |                        |                   |
|------------------------------------------|-----------------------|------------------------|-------------------|
| BMW 1 HATCH: 1VVA728                     |                       |                        |                   |
| Vinnumber:                               | WBA1V710507D59123     | Versionname:           | 116d (85 kW)      |
| First Registrationdate:                  | 8/03/2019             | Fiscalpower:           |                   |
| Expertise Mileage:                       | 148020                | Power Kw:              | 85                |
| Bodytype:                                |                       | Body colour            | Grey              |
| Gearbox:                                 | MAN 6 VIT             | Type of rims (mounted) | Aluminium         |
| Transmission:                            |                       | Parking lot            | 2124              |
| Fueltype:                                | Diesel                |                        |                   |
| Type of rims (mounted)                   | Aluminium             |                        |                   |
| Certificate of Conformity                | Yes                   |                        |                   |
| Category                                 | Passenger Car         |                        |                   |
| Registration Certificate Car (BE)        | Yes                   |                        |                   |
| Registration Certificate Home (BE)       | No                    |                        |                   |
| Options                                  |                       |                        |                   |
| Number of keys total                     | 2                     | Luggage cover          |                   |
| Cruise Control                           |                       | Front parking sensors  |                   |
| Steering wheel multifunctional           |                       | Rear parking sensors   |                   |
| Seats F heated                           |                       | Type of Tow bar        | No Tow bar        |
| Radio multimedia                         |                       |                        |                   |
| Type of headlighting                     | Headlighting LED      |                        |                   |
| Type of GPS                              | GPS big screen color  |                        |                   |
| Type of Lining                           | Lining leather        |                        |                   |
| Type of climate control                  | Autom climate control |                        |                   |
| Limited Technical Inspection             |                       |                        |                   |
| Tyres                                    |                       |                        |                   |
| Summer tyres:                            | 205/50/17/89 V        |                        |                   |
|                                          | Fr.L.                 | Continental: 4 mm      | Fr.R.             |
|                                          | Re.L.                 | Continental: 5 mm      | Re.R.             |
|                                          |                       |                        | Continental: 5 mm |
| Tyre profile depth FL                    |                       |                        | 4.0               |
| Tyre profile depth FR                    |                       |                        | 4.0               |
| Tyre profile depth RL                    |                       |                        | 5.0               |
| Tyre profile depth RR                    |                       |                        | 5.0               |
| Tyre size FL                             |                       |                        | 205/50 R 17 89 V  |
| Tyre size FR                             |                       |                        | 205/50 R 17 89 V  |
| Tyre size RL                             |                       |                        | 205/50 R 17 89 V  |
| Tyre size RR                             |                       |                        | 205/50 R 17 89 V  |
| Tyre type FL                             |                       |                        | Summer            |
| Tyre type FR                             |                       |                        | Summer            |
| Tyre type RL                             |                       |                        | Summer            |
| Tyre type RR                             |                       |                        | Summer            |
| Tyre make FL                             |                       |                        | 256               |
| Tyre make FR                             |                       |                        | 256               |
| Tyre make RL                             |                       |                        | 256               |
| Tyre make RR                             |                       |                        | 256               |
| Assistance equipment                     |                       |                        |                   |
| Number of charging cables (normal)       | 0                     |                        |                   |
| Number of charging cables (rapid charge) | 0                     |                        |                   |
| Total cost ex VAT                        |                       |                        | 129,66            |
| Interior, Damaged, Acceptable            |                       |                        | 0,00              |



|                                     |      |
|-------------------------------------|------|
| Door panel RR, Scratch(es), Replace | 0,00 |
|-------------------------------------|------|



|                                              |      |
|----------------------------------------------|------|
| Windscreen, Stone chip(s), Windscreen repair | 0,00 |
|----------------------------------------------|------|




|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|




|                                       |      |
|---------------------------------------|------|
| Bonnet, Chemical polution, Acceptable | 0,00 |
|---------------------------------------|------|



|                                       |      |
|---------------------------------------|------|
| Alloy rim FL, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|



|                              |      |
|------------------------------|------|
| Door FL, Dent(s), Acceptable | 0,00 |
|------------------------------|------|



|                                    |      |
|------------------------------------|------|
| Wing RL, Chemical polution, Polish | 0,00 |
|------------------------------------|------|



|                              |      |
|------------------------------|------|
| Door RL, Dent(s), Acceptable | 0,00 |
|------------------------------|------|



|                                              |      |
|----------------------------------------------|------|
| Boot lid covering R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------|------|



Bumper R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Door FR, Dent(s), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Roof, Dent(s), Acceptable

0,00

