



BMW 1 HATCH: 1RTU699

|                                    |                   |                         |                                        |
|------------------------------------|-------------------|-------------------------|----------------------------------------|
| Vinnnumber:                        | WBA1V910005G94524 | Versionname:            | 116d EfficientDynamics Edition (85 kW) |
| First Registrationdate:            | 28/02/2017        | Fiscalpower:            |                                        |
| Expertise Mileage:                 | 174796            | Power Kw:               | 85                                     |
| Bodytype:                          |                   | Body colour:            | Blue                                   |
| Gearbox:                           | MAN 6 VIT         | Type of rims (mounted): | Aluminium                              |
| Transmission:                      |                   | Parking lot:            | 3330                                   |
| Fueltype:                          | Diesel            |                         |                                        |
| Type of rims (mounted):            | Aluminium         |                         |                                        |
| Certificate of Conformity:         | Yes               |                         |                                        |
| Category:                          | Passenger Car     |                         |                                        |
| Registration Certificate Car (BE): | Yes               |                         |                                        |

Options

|                                 |                           |                       |            |
|---------------------------------|---------------------------|-----------------------|------------|
| Number of keys total:           | 2                         | Luggage cover:        |            |
| Cruise Control:                 |                           | Rear parking sensors: |            |
| Steering wheel multifunctional: |                           | Type of Tow bar:      | No Tow bar |
| Seats F heated:                 |                           |                       |            |
| Radio multimedia:               |                           |                       |            |
| Type of headlighting:           | Headlighting Halogen      |                       |            |
| Type of GPS:                    | GPS big screen color      |                       |            |
| Type of Lining:                 | Lining artificial leather |                       |            |
| Type of climate control:        | Autom climate control     |                       |            |

Limited Technical Inspection

Degree of wear

|                       |       |                 |                  |
|-----------------------|-------|-----------------|------------------|
| 205/55/16/91 H        |       |                 |                  |
| Winter tyres:         | Fr.L. | Uniroyal: 3 mm  | Fr.R.            |
|                       | Re.L. | Firestone: 4 mm | Re.R.            |
| Tyre profile depth FL |       |                 | 3.0              |
| Tyre profile depth FR |       |                 | 3.0              |
| Tyre profile depth RL |       |                 | 4.0              |
| Tyre profile depth RR |       |                 | 4.0              |
| Tyre size FL          |       |                 | 205/55 R 16 91 H |
| Tyre size FR          |       |                 | 205/55 R 16 91 H |
| Tyre size RL          |       |                 | 205/55 R 16 91 H |
| Tyre size RR          |       |                 | 205/55 R 16 91 H |
| Tyre type FL          |       |                 | Winter           |
| Tyre type FR          |       |                 | Winter           |
| Tyre type RL          |       |                 | Winter           |
| Tyre type RR          |       |                 | Winter           |
| Tyre make FL          |       |                 | 265              |
| Tyre make FR          |       |                 | 265              |
| Tyre make RL          |       |                 | 258              |
| Tyre make RR          |       |                 | 258              |

Assistance equipment

|                                           |     |             |     |
|-------------------------------------------|-----|-------------|-----|
| Repair kit:                               | Yes | Compressor: | Yes |
| Number of charging cables (normal):       | 0   |             |     |
| Number of charging cables (rapid charge): | 0   |             |     |

|                                               |        |
|-----------------------------------------------|--------|
| Total cost ex VAT:                            | 382,13 |
| Windscreen, Stone chip(s), Windscreen repair: | 0,00   |



Door RL, Dent(s), Paintless dent repair

93,06



Wing RL, Scratch(es), Acceptable

0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

289,07



Tailgate / Boot, Dent(s), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00

