



BMW 4er 420d Gran Coupe

VIN NO WBA21AX040FN09651
Registration Number 040FN09651



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-08-01	1	2	172493 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-05-19	151470	2022-08-05	Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20251002093357
Inspection Date / Place	2025-10-02 / BCA Oberndorf	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Coupe	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Ambientlighting	Anti-lock braking
Bluetooth telephone interface	Diesel particulate filter	Digitaldashboard	Parking Assistance
Remote central locking	Satellite navigation	Stability control	Electrically folding wing mirrors
Leather steering wheel	Radio	USB Socket	Alloys wheels
AndroidAuto	AppleCarPlay	Cruise control	Digital Radio
Front parking sensors	Remote adjusting wing mirrors	Reversing Camera	Split folding rear seats
Sunroof	Electrictailgate	LED Headlamps	Rear parking sensors

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Seat Heating	Front	Sunroof Type	Tilt/Slide Glass

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	6
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

7 Schäden



1 Schäden



Component	Damage	Comments
1 Luggage Space Cover / Back	Interior / Scratched	
2 Side Panel / Back Left	Paint / Poor Previous Repair	
3 Fender / Front Left	Paint / Poor Previous Repair	
4 Hood	Paint / Stone Chip	
5 Side Panel / Back Left	Paint / Poor Previous Repair	
6 Bumper / Front	Paint / Scratch / Scuff	
7 Bumper / Front	Paint / Scratch / Scuff	
8 Rim / Back Right	Out of Bodywork / Scratch	




1. Luggage Space Cover / Back Interior / Scratched -



2. Side Panel / Back Left Paint / Poor Previous Repair -



3. Fender / Front Left Paint / Poor Previous Repair -



4. Hood Paint / Stone Chip -



5. Side Panel / Back Left Paint / Poor Previous Repair -



6. Bumper / Front Paint / Scratch / Scuff -



7. Bumper / Front
Paint / Scratch / Scuff -



8. Rim / Back Right
Out of Bodywork / Scratch -

Mechanical Condition

Equipments Test			
Central Locking	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	⚠
Electric Windows	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓
Control Lights			
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓		
Engine			
Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		
Gearbox			
Gear Box	✓		

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly	✓		
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
General			
Test Driven Status	Not Performed		

- ✔ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ❗ *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)