

DEKRA Automotive Solutions

Vehicle details

VIN	WBA21EA00 P7L54231	Brand	BMW	Maintenance date	13/08/2025
Licence Plate	PFY44L	Model	Serie2-ActiveTourer-U06-2021	Maintenance mileage	26 908 km
Registration date	17/10/2022	Year	2022	Exterior Color	Other
Odometer	28 834 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Minivan	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	7		

Inspection Details

Inspection date	07/11/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Charging kit	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions


Tyres

Continental 225/50/18 W Summer 6.0 mm				Continental 225/50/18 W Summer 6.0 mm	
Continental 225/50/18 W Summer 6.0 mm				Continental 225/50/18 W Summer 6.0 mm	

Winter kit

Continental 205/60/17 T Winter 9.0 mm				Continental 205/60/17 T Winter 9.0 mm	
Continental 205/60/17 T Winter 9.0 mm				Continental 205/60/17 T Winter 9.0 mm	

Damages

1		Part	Refill emergency kit	2		Part	Aftermarket wheel
		Position	-			Position	-
3		Damages	Missing	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum replacement	6		Repair mode	For info
		Part	Aftermarket wheel			Part	Bumper moulding
7		Position	-	8		Position	Front right
		Damages	Scratched			Damages	Scratched
9		Severity	-	10		Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Alloy wheel			Part	Wing
		Position	Front left			Position	Back right
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Bumper			Part	Sill
		Position	Back			Position	Right
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumpsum Paintworks

DEKRA Automotive Solutions

<p><b>11</b></p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Alloy wheel</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum replacement</td></tr> </table>	Part	Alloy wheel	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum replacement	<p><b>12</b></p>  <p>● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum replacement</td></tr> </table>	Part	Windscreen	Position	-	Damages	Broken	Severity	-	Repair mode	Lumpsum replacement
Part	Alloy wheel																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum replacement																						
Part	Windscreen																						
Position	-																						
Damages	Broken																						
Severity	-																						
Repair mode	Lumpsum replacement																						