



BMW X1 (UKL): 1XQY531

Vinnumber:	WBA31AA0903M02271	Versionname:	X1 (F48) 18i sDrive 1.5i 136pk/cv 5p
First Registrationdate:	12/03/2020	Fiscalpower:	
Expertise Mileage:	149552	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/97 H				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 17 97 H
Tyre size FR				225/55 R 17 97 H
Tyre size RL				225/55 R 17 97 H
Tyre size RR				225/55 R 17 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0
Bumper F, Scratch(es), Spot repair	



Bumper F, Scratch(es), Smart repair



Bonnet, Scratch(es), Acceptable



Windscreen moulding, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)




Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Door trim RL, Scratch(es), Acceptable



Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Door RR, Dent(s), Paintless dent repair



Door RR, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable





Bodywork, Paint measurement, Acceptable



Roof, Dent(s), Acceptable

