



BMW X1: 1WXN001

Vinnumber:	WBA31AA0X03L37124	Versionname:	
First Registrationdate:	16/10/2019	Fiscalpower:	
Expertise Mileage:	104200	Power Kw:	
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3522
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 1600 km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/50/18/99 V			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
Tyre profile depth FL			6.0
Tyre profile depth FR			4.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/50 R 18 99 V
Tyre size FR			225/50 R 18 99 V
Tyre size RL			225/50 R 18 99 V
Tyre size RR			225/50 R 18 99 V
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1309,70
Bonnet, Chemical polution, Repair and paint (complete)	395,90



Windscreen, Stone chip(s), Windscreen repair

0,00



Door FL, Dent(s), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Boot lid covering R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Roof pillar R, Chemical polution, Repair and paint (complete)

300,51



Sill trim R, Scratch(es), Smart repair

113,74



Door RR, Repaired, Acceptable

0,00



Wing FR, Chemical polution, Repair and paint (complete)

300,51



Roof, Chemical polution, Repair and paint (complete)

0,00

