



BMW X1 (UKL): 2ABK124

Vinnumber:	WBA31AC0105T18429	Versionname:	X1 (F48) 16d sDrive 1.5d 116pk/cv 5p Aut.
First Registrationdate:	9/02/2021	Fiscalpower:	
Expertise Mileage:	122058	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	1100.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/101 W				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 101 W
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0
Ignition key, Missing, Replace	



Seat cover FL, Worn, Acceptable



Door panel RL, Scratch(es), Acceptable



Backrest cover FR, Damaged, Forfeit



Bonnet, Scratch(es), Acceptable



Door FL, Dent(s), Paintless dent repair



Door RL, Dent(s), Acceptable



Wing RL, Dent(s), Paintless dent repair




Wing RL, Dent(s), Acceptable



Door FL, Dent(s), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Compressor, Missing, Check



Tyre repair kit, Missing, Check



Boot lid covering R, Scratch(es), Smart repair



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Paintless dent repair



Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Dent(s), Acceptable



Door RR, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable

