

**BMW X1: 1YMK283**

Vinnumber:	WBA31AC030M63483	Versionname:	sDrive16d (85 kW)
First Registrationdate:	7/10/2020	Fiscalpower:	
Expertise Mileage:	98152	Power Kw:	85
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3309
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection**Tyres**

215/50/18/92 H				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/50 R 18 92 H
Tyre size FR				215/50 R 18 92 H
Tyre size RL				215/50 R 18 92 H
Tyre size RR				225/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1579,03
Seat cover FL, Damaged, Acceptable	0,00



Bonnet, Scratch(es), Repair and paint (complete) 406,19



Brand badge F, Strained, Acceptable 0,00



Door RL, Bad repair, Check 0,00



Step L, Scratch(es), Repair and paint (complete) 161,81



Door RL, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Replace 565,24



Door FR, Dent(s) and scratch(es), Repair and paint (complete)	445,79
---	--------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------

