

Inspection report

BMW X1

WBA31AE01N5T60295

[View provider inspection](#)



+16 Pictures
& 360°

Description

Registration number

AAAA 123

Odometer

53677

Color

BLACK SAPPHIRE METALLIC

Doors

5

Upholstery

-

Registration date

-

Year

-

Transmission

automatic transmission - with Steptronic (8-speed)

Seats

5

Statement details

Inspection location

HN - MYWAY PRO (DIETEREN)

Statement date

15/10/2024

Inspection approval date

16/10/2024

Defects & corrections



Aile Avant Gauche 10



Porte Arrière Gauche 14



No pictures

Porte Avant Gauche 59



No pictures

Porte Arrière Gauche 59



Garniture de jupe - 11



Garniture de hayon ou malle - 11



Montant de pavillon Droit 11



No pictures

Pare-chocs Arrière 59




Porte Avant Droit 11



Moteur - 22



Capot - 12



Pare-brise - 12



Lame spoiler Avant 11