

DEKRA Automotive Solutions

Vehicle details

VIN	WBA31AH05 MCH18927	Brand	BMW	Maintenance date	17/04/2024
Licence Plate	ALS21Y	Model	Serie5Lim-G30-2016	Maintenance mileage	30 294 km
Registration date	27/05/2021	Year	2021	Exterior Color	Other
Odometer	36 306 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	8		

Inspection Details

Inspection date	17/01/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Refill emergency kit	✗
----------------------	---

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions

Tyres

Goodyear 245/40/19 Y Summer 6.0 mm		Goodyear 245/40/19 Y Summer 6.0 mm	
Goodyear 245/40/19 Y Summer 6.0 mm		Goodyear 245/40/19 Y Summer 6.0 mm	

Winter kit

Nokian 245/45/18 T Winter 8.0 mm		Nokian 245/45/18 T Winter 7.0 mm	
Nokian 245/45/18 T Winter 7.0 mm		Nokian 245/45/18 T Winter 8.0 mm	

Damages

1



Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2



Part	Bumper
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

3



Part	Registration plates
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum replacement

4



Part	Alloy wheel
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

5



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

6



Part	Alloy wheel
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Polishing

8



Part	Alloy wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

9



Part	Door sill
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

10



Part	Turning signal side
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info