



BMW 2 GRAN COUPÉ: 1YQT593			
Vinnumber:	WBA31AM0707H21286	Versionname:	218d (100kW)
First Registrationdate:	9/11/2020	Fiscalpower:	
Expertise Mileage:	107973	Power Kw:	100
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2721
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	225/40/18/92 Y		
	Fr.L.	Vredestein: 5 mm	Fr.R. Vredestein: 4 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			4.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/40 R 18 92 Y
Tyre size FR			225/40 R 18 92 Y
Tyre size RL			225/40 R 18 92 Y
Tyre size RR			225/40 R 18 92 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2331,22
Ignition key, Missing, Replace			341,22



Interior, Dirty, Cleaning

170,61



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Windscreen, Scratch(es), Replace

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Sill trim L, Scratch(es), Polish

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Wing RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------




Rear window, Scratch(es), Replace	0,00
-----------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)	300,51
---	--------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------




Step R, Dent(s) and scratch(es), Spot repair	144,58
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Sill trim R, Scratch(es), Acceptable	0,00
--------------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------

