



BMW Serie 3 F31 2012 Touring Diese 320d Touring Modern

VIN NO WBA3K31020F662535
Registration Number ER600JZ



MOT Date

2025-03-25

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2013-03-12

Odometer Reading



149702 km

Country First Registered



Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251003110736
Inspection Date / Place	2025-10-03 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	124

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Satellite navigation
Parcel Shef	Remote central locking	Stability control	Power assisted steering
Alloys wheels	Electrically folding wing mirrors	Volante multifuncion	Remote adjusting wing mirrors

Trip Computer


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	GOODYEAR GOODYEAR-EAGLE F1 ASYMMETRIC	225/45//R18 - 95Y / 3 mm
	GOODYEAR GOODYEAR-EAGLE F1 ASYMMETRIC	225/45//R18 - 95Y / 3 mm
	GOODYEAR GOODYEAR-EAGLE F1 ASYMMETRIC 2	225/45//R18 - 95Y / 3 mm
	GOODYEAR GOODYEAR-EAGLE F1 ASYMMETRIC 2	225/45//R18 - 95Y / 3 mm

Cosmetic Damage

22 Danni



2 Danni



Component		Damage	Comments
1	Dashboard / Front	Interior / Warning Light ON	
2	Interior door handle Front left	Interior / Broken	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Paint / Scratch / Line	
5	Hood	Bodywork / Poor Previous Repair	
6	Bumper / Front	Bodywork / Dent	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Mirror Shell / Front Left	Paint / Scratch / Line	
9	Door / Front Left	Paint / Scratch / Line	
10	Door / Back Left	Bodywork / Dent	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Fender / Back Left	Paint / Scratch / Line	


13	Bumper / Back	Bodywork / Dent
14	Tailgate	Paint / Scratch / Line
15	Fender / Back Right	Bodywork / Poor Previous Repair
16	Rim / Back Right	Out of Bodywork / Scratch
17	Door / Back Right	Bodywork / Dent
18	Door / Back Right	Bodywork / Dent
19	Door / Front Right	Bodywork / Poor Previous Repair
20	Mirror Shell / Front Right	Paint / Scratch / Line
21	Fender / Front Right	Bodywork / Poor Previous Repair
22	Rim / Front Right	Out of Bodywork / Scratch
23	Pillar / Front Right	Bodywork / Poor Previous Repair
24	Roof	Bodywork / Dent / Hail Area




1. Dashboard / Front Interior / Warning Light ON -



2. Interior door handle Front left Interior / Broken -



3. Windshield / Front Glass Break / Impact -




4. Hood Paint / Scratch / Line -




5. Hood Bodywork / Poor Previous Repair -




6. Bumper / Front Bodywork / Dent -




7. Rim / Front Left
Out of Bodywork / Scratch -




8. Mirror Shell / Front Left
Paint / Scratch / Line -



9. Door / Front Left
Paint / Scratch / Line -




10. Door / Back Left
Bodywork / Dent -




11. Rim / Back Left
Out of Bodywork / Scratch -




12. Fender / Back Left
Paint / Scratch / Line -




13. Bumper / Back
Bodywork / Dent -



14. Tailgate
Paint / Scratch / Line -



15. Fender / Back Right
Bodywork / Poor Previous Repair -



16. Rim / Back Right
Out of Bodywork / Scratch -




17. Door / Back Right
Bodywork / Dent -



18. Door / Back Right
Bodywork / Dent -




19. Door / Front Right
Bodywork / Poor Previous Repair -



20. Mirror Shell / Front Right
Paint / Scratch / Line -



21. Fender / Front Right
Bodywork / Poor Previous Repair -



22. Rim / Front Right
Out of Bodywork / Scratch -



23. Pillar / Front Right
Bodywork / Poor Previous Repair -



24. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	!
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA FRENI ACCESA.
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			