



# BMW 3er 320d Touring Aut.

VIN NO WBA3K31060F654776  
Registration Number 060F654776



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-12-01	2	2	191517 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-05-06	189395	2013-01-15	Germany

## Inspection Report Summary


Customer	BCA Online	Report Number	P20250923085316
Inspection Date / Place	2025-09-23 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

## Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	123
Gearbox Type	Automatic		

## Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









## Equipment

Trip Computer	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Diesel particulate filter	Remote adjusting wing mirrors	Roof rails	Stability control
Electrictailgate	Radio	USB Socket	Alloys wheels
Auxiliary Socket	Cruise control	Front parking sensors	Remote central locking
Satellite navigation	CD Player	Leather steering wheel	Rear parking sensors

## Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front


## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6




Cosmetic Damage

17 Schäden



1 Schäden



Component		Damage	Comments
1	Hood	Paint / Scratch / Scuff	
2	Bumper / Front	Bodywork / Dent / Dent	
3	Rim / Front Left	Out of Bodywork / Scratch	
4	Door / Front Left	Paint / Scratch / Scuff	
5	Rim / Back Left	Out of Bodywork / Scratch	
6	Fender / Back Left	Bodywork / Dent / Dent	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Rear Window / Back	Glass Break / Scratch / Scratch	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Fender / Back Right	Bodywork / Dent / Dent	
11	Rim / Back Right	Out of Bodywork / Scratch	
12	Door / Back Right	Bodywork / Dent / Dent	

13	Rim / Front Right	Out of Bodywork / Scratch
14	Mirror / Front Right	Paint / Scratch / Scuff
15	Door / Front Right	Bodywork / Dent / Dent
16	Pillar / Front Left	Bodywork / Dent / Dent
17	Seat / Front Left	Interior / Scratched
18	Tailgate	Paint / Scratch / Scuff



1. Hood  
Paint / Scratch / Scuff -



2. Bumper / Front  
Bodywork / Dent / Dent -




3. Rim / Front Left  
Out of Bodywork / Scratch -



4. Door / Front Left  
Paint / Scratch / Scuff -




5. Rim / Back Left  
Out of Bodywork / Scratch -



6. Fender / Back Left  
Bodywork / Dent / Dent -







7. Bumper / Back  
Paint / Scratch / Scuff -



8. Rear Window / Back  
Glass Break / Scratch / Scratch -




9. Bumper / Back  
Paint / Scratch / Scuff -



10. Fender / Back Right  
Bodywork / Dent / Dent -



11. Rim / Back Right  
Out of Bodywork / Scratch -



12. Door / Back Right  
Bodywork / Dent / Dent -






13. Rim / Front Right  
Out of Bodywork / Scratch -



14. Mirror / Front Right  
Paint / Scratch / Scuff -



15. Door / Front Right  
Bodywork / Dent / Dent -



16. Pillar / Front Left  
Bodywork / Dent / Dent -



17. Seat / Front Left  
Interior / Scratched -



18. Tailgate  
Paint / Scratch / Scuff -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)