



BMW SERIE 4

Coupe 430d xDrive 258 ch M Sport A

VIN NO WBA3S31000K698358
Registration Number EF966FQ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	85437 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-09-15	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250926113758
Inspection Date / Place	2025-09-26 / BCA MONTMARTIN	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	2993
Engine Size	3.0	No of Doors	2
Body Type	Coupe	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	4
Charging Cables		NEDC CO2 Rating (q/km)	142

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Stability control
Cruise control	Front parking sensors	Satellite navigation	Electrically adjustable seats
Radio	Alloys wheels	Tow ball	Front fog lamps

Power assisted steering

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		

Wheels & Tyres


Left Rear Tyre Depth	3	Left Front Tyre Depth	2
Right Rear Tyre Depth	3	Right Front Tyre Depth	2
Tyres Comment	Douille écrou antivol absente		

Cosmetic Damage


11 Dommages



1 Dommages




Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Rim	Out of Bodywork / Scratch	
3	Door / Front Left	Paint / Scratch / Line	
4	Rim	Out of Bodywork / Scratch	
5	Corner Bumper / Back Right	Paint / Scratch / Scuff	
6	Rim Brake pads	Out of Bodywork / Scratch	
7	Fender / Back Right	Paint / Scratch / Scuff	
8	Door / Front Right	Paint / Scratch / Scuff	
9	Rim	Out of Bodywork / Scratch	
10	Fender / Front Right	Paint / Scratch / Line	
11	Corner Bumper / Front Left	Paint / Scratch / Scuff	
12	Hood	Bodywork / Dent / Deformation	




1. Floor Carpet
Interior / Dirty -



2. Rim
Out of Bodywork / Scratch -



3. Door / Front Left
Paint / Scratch / Line -



4. Rim
Out of Bodywork / Scratch -



5. Corner Bumper / Back Right
Paint / Scratch / Scuff -



6. Rim Brake pads
Out of Bodywork / Scratch -



7. Fender / Back Right
Paint / Scratch / Scuff -



8. Door / Front Right
Paint / Scratch / Scuff -



9. Rim
Out of Bodywork / Scratch -



10. Fender / Front Right
Paint / Scratch / Line -



11. Corner Bumper / Front Left
Paint / Scratch / Scuff -











12. Hood
Bodywork / Dent / Deformation -

Mechanical Condition









Tyres

Presence Anti-Theft Lock Nut 


Dashboard Lights

ABS Warning Light		Diesel Particulate Filter Light	NA
4WD Light	NA	Dashboard Working	
Engine Light		Oil Pressure Warning Light	
Airbag Warning Light		Brake Warning Light	
Level - Fuel / Battery	25	Transmission Warning Light	NA
ESP Fault/Traction Control Malfunction Light		Service Light	
Steering Fluid Level	NA		

Equipments Test

Electric Windows		Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	
Central Locking		Audio Equipment	
Navigation System		AC / Heating System	
Parking Sensors / Cameras Functioning			

Levels

Oil - Condition	NA	Level - Oil	Not available
Coolant Fluid - Condition		Coolant Fluid	
Brakes Fluid			

Engine

Cross Member		Serpentine Belt	
Control Liquid Leak			

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
-----------------------	----	--	----

Test Drive Inspection

Test Drive			
Vehicle Starts	✓	Engine functioning	✓
Engine / Aux Belt / Pulley Noise	✓	Steering Noise/Gripping	✓
Smoke Quantity	✓	Transmission	✓
Engine Power	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.