



BMW SERIE 4 GRAN COUPE

Gran Coupe 430i xDrive 252 ch Lounge A

VIN NO WBA4E11010G184943
Registration Number ED692LH



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	55939 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-06-28	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250922075128
Inspection Date / Place	2025-09-22 / BCA BOUCHAIN	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	Hatchback	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	138

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Radio	Alloys wheels	Cruise control
Power assisted steering	Electrically folding wing mirrors	Rear parking sensors	Stability control
Front fog lamps	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	6	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Right Front Tyre Depth	5

Cosmetic Damage

5 Dommages



0 Dommages




Component		Damage	Comments
1	Rim / Front Left	Out of Bodywork / Scratch	
2	Bumper / Back	Paint / Scratch / Line	
3	Rim / Back Right	Out of Bodywork / Scratch	
4	Door / Front Right	Paint / Scratch / Line	
5	Rim / Front Right	Out of Bodywork / Scratch	




1. Rim / Front Left
Out of Bodywork / Scratch -



2. Bumper / Back
Paint / Scratch / Line -



3. Rim / Back Right
Out of Bodywork / Scratch -



4. Door / Front Right
Paint / Scratch / Line -



5. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Levels

Coolant Fluid - Condition	✓	Oil - Condition	✓
Level - Oil	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Tyres

Presence Anti-Theft Lock Nut ✓

Dashboard Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Diesel Particulate Filter Light	NA
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	20
Transmission Warning Light	✓	Service Light	✓
Steering Fluid Level	NA		

Equipments Test

Electric Windows	✓	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	✓
Central Locking	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓		

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

Engine

Cross Member	✓	Serpentine Belt	✓
--------------	---	-----------------	---

Control Liquid Leak ✓

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Vehicle Starts	✓	Steering Noise/Gripping	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.