



BMW 418: K436HK

Vinnumber:	WBA4H11020CF52435	Versionname:	418iA 100kW M Sport Corporate lease gran coupe
First Registrationdate:	2/01/2021	Fiscalpower:	
Expertise Mileage:	34409	Power Kw:	100
Bodytype:		Body colour:	Saphirschwarz metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	35
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining Alcantara
GPS		Sun Roof electric
GPS storage		Panoramic roof
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

225/40/19/93 Y				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/40 R 19 93 Y
Tyre size FR				225/40 R 19 93 Y
Tyre size RL				225/40 R 19 93 Y
Tyre size RR				225/40 R 19 93 Y
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Alloy rim FL, Scratch(es), Repair and paint (complete)





Alloy rim RL, Scratch(es), Repair and paint (complete)



Door RL, Chemical polution, Polish



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)





Alloy rim RR, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Chemical polution, Polish



Bodywork, Paint measurement, Acceptable

