


Vehicle details

VIN	WBA51BN01 0CG03464	Brand	BMW	Maintenance date	-
Licence Plate	MD934LJ	Model	Series 5 520d A xDrive Touring 140KW	Maintenance mileage	-
Registration date	20/01/2021	Year	1000	Exterior Color	Black Metallic
Odometer	231 189 km	Engine size	1995	interior Color	Blue
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/01/2026
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	06/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Xenon projectors	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓

Removable element



Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Continental 225/55/17 V Winter 8.8 mm			Continental 225/55/17 V Winter 8.6 mm	
Continental 225/55/17 V Winter 8.0 mm			Continental 225/55/17 V Winter 7.9 mm	

Exterior

1



PartBumper

PositionFront

DamagesBroken

Severity-

Repair modeReplace a2

2



PartWing

PositionFront left

DamagesDent & Chips

Severity-

Repair modeReplace

3



PartDoor

PositionFront left

DamagesDent & Chips

Severity-

Repair modeRepair

4



PartDoor

PositionBack left

DamagesDent & Chips

Severity-

Repair modeRepair

5



PartWing

PositionBack left

DamagesDent & Chips

Severity-

Repair modeReplace

6



PartAlloy wheel 17"

PositionFront left

DamagesScratched

Severity-

Repair modeSmart Repair

7



PartAlloy wheel 17"

PositionBack left

DamagesScratched

Severity-

Repair modeSmart Repair

9



PartDoor sill


PositionBack left

DamagesDent & Chips

Severity-

Repair modeRepair

10



PartRear parking sensor

PositionFront left

DamagesScratched

Severity-

Repair modeReplace

11



PartBumper

PositionBack

DamagesScratched

Severity-

Repair modeRepair a2

12



PartMoulding spoiler

PositionBack

DamagesDeformed

Severity-

Repair modeReplace

13



PartWing

PositionBack right

DamagesDent & Chips

Severity-

Repair modeRepair

14



PartDoor

PositionBack right

DamagesScratched

Severity-

Repair modeRepair

15



PartDoor

PositionFront right

DamagesScratched

Severity-

Repair modeRepair

16



PartWing

PositionFront right

DamagesDent & Chips

Severity-

Repair modeReplace

17



PartTurning signal side

PositionRight

DamagesScratched

Severity-

Repair modeReplace a2

18



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

19



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

21



Part	Sill cover
Position	Right
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

8



●●

Part	Seat plastic trim
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

20



●●

Part	Interior roof lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Replace

22



●●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

Others

23

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

24

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks