


DEKRA Automotive Solutions

Vehicle details

VIN	WBA51BN0X MCH28534	Brand	BMW	Maintenance date	27/01/2025
Licence Plate	MGN94A	Model	Serie-5-Touring-G31-2017	Maintenance mileage	102 074 km
Registration date	15/07/2021	Year	2021	Exterior Color	Other
Odometer	121 019 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Load cover	✓
Towing hook	✓
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions

Tyres

Goodyear 245/45/18 Y Summer 5.0 mm		Goodyear 245/45/18 Y Summer 5.0 mm	
Goodyear 245/45/18 Y Summer 3.0 mm		Goodyear 245/45/18 Y Summer 3.0 mm	

Winter kit

Pirelli 225/55/17 T Winter 8.0 mm		Pirelli 225/55/17 T Winter 8.0 mm	
Pirelli 225/55/17 T Winter 8.0 mm		Pirelli 225/55/17 T Winter 8.0 mm	

Damages

1

Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

3

Part	Bumper grille
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

4

Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

5

Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

6

Part	Bumper
Position	Back
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

7

Part	Tailgate / Boot door
Position	Back
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

8

Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

9

Part	Bumper grille
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

10

Part	Windscreen
Position	Front
Damages	Stone impact
Severity	-
Repair mode	Smart Repair