


### Vehicle details

VIN	WBA5P510X 0FK28692	Brand	BMW	Maintenance date	-
Licence Plate	J3-38-TX	Model	3 Serie Sedan 330e Business Edition Plus 4d	Maintenance mileage	-
Registration date	20/10/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	200 544 km	Engine size	1998	interior Color	Brown
Fuel	Hybrid petrol	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

### Inspection Details

Inspection date	01/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

### Removable element

Vehicle charger	✓
Wireless charger	✓

### Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

### Tyres





Continental 255/35/19 Summer 4.5 mm

Continental 255/35/19 Summer 5.0 mm

Pirelli 255/35/19 Summer 7.5 mm

Pirelli 255/35/19 Summer 7.5 mm

### Exterior

1		<table border="0"> <tr><td>Part</td><td>Alloy wheel 19"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 19"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	2		<table border="0"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Windscreen	Position	-	Damages	Broken	Severity	-	Repair mode	Replace
Part	Alloy wheel 19"																								
Position	Front left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Windscreen																								
Position	-																								
Damages	Broken																								
Severity	-																								
Repair mode	Replace																								