

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	293430
License plate	2ANR723
Vehicle identification number	WBA5W71000FL41145
Dossier	2021039021
Make	BMW 316d 90kW Aut.
Mileage	84964
First registration	11/06/2021
client availability date	04/09/2025
inspectionDate	11/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
153	Rear Bonnet // Painting	Y
183	Wing Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y

Damage Pictures



Rear Bonnet // Painting-scratch




Wing Rear Right // Painting-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Polish-scratch




Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Bumper Front // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent