

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	293701
License plate	2AWH991
Vehicle identification number	WBA5Y91070FL83141
Dossier	2021 160 093
Make	BMW 320e
Mileage	138540
First registration	16/08/2021
client availability date	08/09/2025
inspectionDate	12/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	N
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	Y
107	Door Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
162	Roof // Painting	N
311	Wheel Alloy Front Left // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures





Door Rear Left / Trim / Replace-scratch





Door Front Left / Trim / Replace-scratch




Wheel Alloy Front Left // Repair-scratch



Bumper Rear // Painting-bad repair



Roof // Painting-Chemical reaction



Interior Cleaning // Small-stain




Bumper Front / Grid Central / Replace-scratch






Bumper Front // Repair & Painting-dent



Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent