



BMW 218 COU PET AUT: WS8050

Vinnnumber:	WBA61CM0608E77889	Versionname:	
First Registrationdate:	4/12/2024	Fiscalpower:	
Expertise Mileage:	33790	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Back		
Fueltype:	Petrol		
Maintenance	OK		
Number of doors	2		
Number of seats	4		
Number head rests	4		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1
Number keys remote	1
Type of GPS	GPS big screen color
Type of GPS storage	HD

Tyres

225/50/17/98 H				
Winter tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 2 mm	Re.R.	Hankook: 2 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	2.0			
Tyre profile depth RR	2.0			
Tyre size FL	225/50 R 17 98 H			
Tyre size FR	225/50 R 17 98 H			
Tyre size RL	225/50 R 17 98 H			
Tyre size RR	225/50 R 17 98 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	260			
Tyre make FR	260			
Tyre make RL	260			
Tyre make RR	260			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Bumper spoiler F, Scratch(es), Replace



Tyre RL, Worn, Replace



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door RL, Repaired, Check



Wing RL, Bad repair, Repair and paint (complete)



Bumper R, Scratch(es), Spot repair



Bumper spoiler Rear, Scratch(es), Spot repair



Tailgate / Boot, Chemical polution, Polish



Wing RR, Dent(s), Paintless dent repair



Tyre RR, Worn, Replace



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Mirror side repeater R, Scratch(es), Replace



Bodywork, Paint measurement, Check

