



BMW 3-Reeks (KLL): 2BEL495

Vinnumber:	WBA6L31030FL93391	Versionname:	318d Touring (G21) 2.0d 136pk/cv 5p Aut.
First Registrationdate:	21/10/2021	Fiscalpower:	
Expertise Mileage:	171993	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	225/50 R 17 98 Y
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	7.0
Tyre profile depth RR	4.0
Tyre size FR	225/50 R 17 98 Y
Tyre make FR	2477

225/50/17/98 Y

Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Tyre size RR	225/50 R 17 98 Y
Tyre make RR	2484
Tyre profile depth FL	7.0
Tyre size FL	225/50 R 17 98 Y
Tyre make FL	2477
Tyre profile depth RL	4.0
Tyre type FR	Summer
Tyre type RR	Summer
Tyre make RL	2484

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Smell, Ozone treatment



Floor covering FL, Burned, Smart repair



Bumper F, Scratch(es), Acceptable



Outside rear-view mirror housing L, Crack, Replace



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Acceptable

