



BMW 3er 320d Touring Aut.

VIN NO WBA6L51000FJ23353
Registration Number 000FJ23353



MOT Date

2026-10-01

Last Service

2024-10-31

Number of Owners

2

Last Service Mileage

165220

Number of Keys

2

First Registration Date

2020-01-29

Odometer Reading

175018 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250721143151
Inspection Date / Place	2025-07-21 / BCA Heidenheim	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	No
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	114
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warranty			







Equipment

Tinted Glass	Airbag Status	Ambientlighting	Anti-lock braking
Bluetooth telephone interface	Diesel particulate filter	Digitaldashboard	Front parking sensors
Parking Assistance	Remote central locking	Roof rails	Split folding rear seats
Electrically adjustable seats	Electrictailgate	Leather steering wheel	Radio
Tow ball	Alloys wheels	AndroidAuto	AppleCarPlay
Cruise control	Digital Radio	Front fog lamps	Head up Display
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Keyless Entry	LED Headlamps	Rear parking sensors

Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	16	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

6 Schäden



2 Schäden



Component		Damage	Comments
1	Pillar / Back Right	Paint / Scratch / Scuff	
2	Side Window / Front Right	Bodywork / Assembly	
3	Center Console	Interior / Scraped	
4	Luggage Space Cover / Back	Interior / Missing	
5	Door / Front Left	Paint / Poor Previous Repair	
6	Hood	Paint / Stone Chip	
7	Hood	Bodywork / Dent / Dent	
8	Side Panel / Back Right	Bodywork / Dent / Dent	



1. Pillar / Back Right
Paint / Scratch / Scuff -



2. Side Window / Front Right
Bodywork / Assembly -




3. Center Console
Interior / Scraped -




4. Luggage Space Cover / Back
Interior / Missing -



5. Door / Front Left
Paint / Poor Previous Repair -



6. Hood
Paint / Stone Chip -



7. Hood
Bodywork / Dent / Dent -



8. Side Panel / Back Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Test Drive Inspection

Steering Wheel

Steering Noise / Anomaly	✓
----------------------------	---

Engine

Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓

General

Test Driven Status	✓
--------------------	---

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

❗ **Damages or malfunction detected that requires repairs by the buyer**

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)