



BMW 3-Reeks (KKL): 2ASN850

Vinnumber:	WBA6M51080FL26021	Versionname:	316d Touring (G21) 2.0d 122pk/cv 5p Aut.
First Registrationdate:	1/07/2021	Fiscalpower:	
Expertise Mileage:	172519	Power Kw:	90
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	01/05/2026		
Maintenance	11000.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/50/17/98 Y			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 4,6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6,2 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.6
Tyre profile depth RL				6.0
Tyre profile depth RR				6.2
Tyre size FL				225/50 R 17 98 Y
Tyre size FR				225/50 R 17 98 Y
Tyre size RL				225/50 R 17 98 Y
Tyre size RR				225/50 R 17 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Ignition key, Not functioning (well), Check



Instrument panel, complete, Not functioning (well), Check



Floor covering FL, Worn, Acceptable



Seat cover FL, Worn, Check



Seat cover FR, Stain, Cleaning



Armrest, Not functioning (well), Check



Engine, Not functioning (well), Check



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Wing RL, Repaired, Check



Wing FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Wing RL, Scratch(es), Acceptable



Tyre repair kit, Missing, Check



Boot lid covering R, Worn, Acceptable



Alloy rim FR, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Wing RR, Dent(s), Paintless dent repair



Door RR, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check

