

Vehicle details

VIN	WBA6N3107 0FL08627	Brand	BMW	Maintenance date	-
Licence Plate	K7-67-VP	Model	3 Serie Touring 330e 5d	Maintenance mileage	-
Registration date	26/03/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	123 143 km	Engine size	1998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Load cover	✓
Vehicle charger	✗
Wireless charger	✗

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 225/50/17 Run-flat 7.0 mm




Pirelli 225/50/17 Run-flat 7.0 mm



Winter kit

Michelin 225/50/17 Winter 4.0 mm



Michelin 225/50/17 Winter 4.0 mm



Exterior

1



Part	Windscreen
Position	-
Damages	Broken
Severity	-
Repair mode	Replace

2



Part	Bonnet
Position	-
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



Part	Tailgate / Boot door
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

8



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

11



Part	Rear (wing) lamp glass
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

12



Part	Bumper moulding
Position	Back right
Damages	Misaligned
Severity	-
Repair mode	Adjust



Others

9		Part	Vehicle charger	10		Part	Wireless charger
		Position	-			Position	-
		Damages	Missing			Damages	Missing
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	For info