



BMW 330e: J496PZ

Vinnnummer:	WBA6N31090FK24017	Versionname:	330eA 215kW touring
First Registrationdate:	8/10/2020	Fiscalpower:	
Expertise Mileage:	175793	Power Kw:	135
Bodytype:		Body colour:	Schwarz II
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	213
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Degree of wear

	225/50/17/94 H			
Winter tyres:	Fr.L.	Bridgestone: 3,7 mm	Fr.R.	Bridgestone: 7,7 mm
	Re.L.	Bridgestone: 5,8 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				3.7
Tyre profile depth FR				7.7
Tyre profile depth RL				5.8
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 17 94 H
Tyre size FR				225/50 R 17 94 H
Tyre size RL				225/50 R 17 94 H
Tyre size RR				225/50 R 17 94 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	0

Roof liner, Stain, Cleaning





Interior, Stain, Cleaning



Seat cover RR, Worn, Replace



Backrest cover RR, Worn, Replace



Door panel RR, Scratch(es), Replace



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Charging cable (fast), Missing, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Rear spoiler, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Roof rail R, Scratch(es), Replace

