


DEKRA Automotive Solutions

Vehicle details

VIN	WBA6N7100 NFN06562	Brand	BMW	Maintenance date	03/04/2025
Licence Plate	SGJ47W	Model	Serie3-Touring-G21-2019	Maintenance mileage	61 607 km
Registration date	01/07/2022	Year	2022	Exterior Color	Other
Odometer	69 982 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Led lighting	✓

Removable element

Towing hook	✓
Refill emergency kit	✗
Load cover	✗

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Pirelli 225/45/18 Y Summer 5.0 mm		Pirelli 225/45/18 Y Summer 5.0 mm	
Michelin 255/40/18 Y Summer 6.0 mm		Michelin 255/40/18 Y Summer 6.0 mm	

Winter kit

Goodyear 225/50/17 T Winter 9.0 mm		Goodyear 225/50/17 T Winter 9.0 mm	
Goodyear 225/50/17 T Winter 9.0 mm		Goodyear 225/50/17 T Winter 9.0 mm	

Damages

1

Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2

Part	Load cover
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4

Part	Wing
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

5

Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Polishing

6

Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

7

Part	Wing
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

8

Part	Bonnet
Position	-
Damages	Dented
Severity	-
Repair mode	Smart Repair two repairs

9

Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	For info