

Inspection Protocol

BMW 330E XDRIVE TOURING

Vehicle information

License plate	TNK56H	Inspected by	C.C.
Year model	2022	Date of inspection	2025-10-23
Manuf. year/month	2022-06	City	Björkvik
First day in traffic	2022-06	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	100 350 km	Latest service	2025-06-13
Fuel	Elhybrid	Mileage at the latest service	89 990 km
Transmission	Steptronic	Summer tires	18" alu-fälg 3/3/5/5
Engine effect	215 kW	Winter tires	alu-fälg odubbbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Other, Other	Other	Snedslitna bakdäck	-
Rims, Aluminum rim	Damage		220 €
Skärm , Rear left	Repa/Repor		260 €
Bumper, Rear	Repa/Repor		260 €
Glass, Windshield	Stenskott/Spricka	Det finns ingen skadeanmälan	510 €

Total excl. VAT 1 250 €

Images

[See all images in large format](#)





















Övrigt Övrigt Övrigt Snedslitna bakdäck















Fälgar Aluminiumfälg Skada 3 000 kr




Skärm Vänster bak Repa/Repor 3 500 kr





Stötfångare Bak Repa/Repor 3 500 kr





Glas Vindruta Stenskott/Spricka Det finns ingen skadeanmälan 7 000 kr