

Inspection data

Inspection date **20/02/2026 17:14**

Vehicle data

License plate **N396TS**
 Make / Type **BMW 3 SERIE TOURING**
 VIN **WBA6N91030FM26676**
 First registration date **14/01/2022**
 Mileage **109,952 km**



Total net costs to be invoiced

€ 135.00

(no VAT applicable)

Gross repair costs in €

Net costs in €

Claim(s) own risk to be invoiced

€ 869.86

€ 135.00

Rear Right

Part	Condition	Repair Description	Gross Repair Cost (€)	Net Cost (€)
Bumper R	Broken	Replace and paint	608.66	135.00
Rear light R	Broken	Replace	97.66	0.00
Parking sensor R	Scratch(es)	Replace and paint	80.00	0.00
Bumper moulding RR	Missing	Replace	71.47	0.00
Reflector	Broken	Replace	12.07	0.00


Not invoiced

€ 785.58

€ 0.00

Part	Condition	Repair Description	Gross Repair Cost (€)	Net Cost (€)
Door FL	Dent(s) and scratch(es)	Repair and paint (complete)	367.79	0.00
Door FR	Dent(s)	Repair and paint (complete)	367.79	0.00
Alloy rim FL	Scratch(es)	Repair and paint (complete)	50.00	0.00

Vehicle pictures





Tires



Location	Position	Depth	Dimension	Make	Type
Front	Left	6.0 mm	225/50 R 17 94 H	Michelin	Winter
Front	Right	5.0 mm	225/50 R 17 94 H	Michelin	Winter
Rear	Left	3.0 mm	225/50 R 17 94 H	Michelin	Winter
Rear	Right	4.0 mm	225/50 R 17 94 H	Michelin	Winter

Damages with pictures



Claim(s) own risk to be invoiced	Gross repair costs in €	Net costs in €
	€ 869.86	€ 135.00

Rear Right



Part	Condition	Repair Description	Gross repair costs in €	Net costs in €
Bumper R	Broken	Replace and paint	608.66	135.00



Part	Condition	Repair Description	Gross repair costs in €	Net costs in €
Rear light R	Broken	Replace	97.66	0.00



Part	Condition	Repair Description	Gross repair costs in €	Net costs in €
Parking sensor R	Scratch(es)	Replace and paint	80.00	0.00

Part	Condition	Repair Description	Gross repair costs in €	Net costs in €
Bumper moulding RR	Missing	Replace	71.47	0.00

Part	Condition	Repair Description	Gross repair costs in €	Net costs in €
Reflector	Broken	Replace	12.07	0.00

Not invoiced	Gross repair costs in €	Net costs in €
	€ 785.58	€ 0.00

Door FL	Dent(s) and scratch(es)	Repair and paint (complete)	367.79	0.00
---------	-------------------------	-----------------------------	--------	------



Door FR	Dent(s)	Repair and paint (complete)	367.79	0.00
---------	---------	-----------------------------	--------	------



Alloy rim FL	Scratch(es)	Repair and paint (complete)	50.00	0.00
--------------	-------------	-----------------------------	-------	------

