

INSPECTION REPORT




End of contract

GENERAL INFO

File	295538
License plate	1XXL169
Vehicle identification number	WBA6T510607G16211
Dossier	2020 073 038
Make	BMW 216d Act.Tourer 85kW Aut.
Mileage	88767
First registration	23/08/2020
client availability date	01/10/2025
inspectionDate	09/10/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
92	Rocker Panel Left // Painting	N
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
13	Bumper Front // Painting	N
271	Bumper Front / Trim Left / Replace	N
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
71	Side View Mirror Left // Plastic Repair	N
80	Door Front Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	N
183	Wing Rear Right // Painting	N
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
451	Seat Rear Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Damage within Renta-norm-scratch




Side View Mirror Right // Painting-scratch




Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Plastic Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Bumper Rear // Smart Repair Medium-scratch



Wheel Alloy Rear Left // Repair-scratch



Seat Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Right // Repair-scratch




Wing Rear Left // Repair & Painting-scratch + dent




Door Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Painting-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Painting-scratch





Door Rear Right // Repair & Painting-scratch



Door Front Right // Repair & Painting-scratch + dent